



SHEET METAL CONVERSION CHART
(For Reference Only)

GAUGE NO.	STAINLESS STEEL GAUGE DECIMAL (INCHES)	CARBON STEEL GAUGE DECIMAL (INCHES)
7	0.1874	0.1793
8	0.1650	0.1644
10	0.1350	0.1345
11	0.1200	0.1196
12	0.1054	0.1046
13	0.0900	0.0897
14	0.0751	0.0747
16	0.0595	0.0598
18	0.0480	0.0478
19	0.0420	0.0418
20	0.0355	0.0359

GAUGE NO.	STAINLESS STEEL GAUGE DECIMAL (CENTIMETERS)	CARBON STEEL GAUGE DECIMAL (CENTIMETERS)
7	0.4760	0.4552
8	0.4190	0.4176
10	0.3429	0.3416
11	0.3048	0.3038
12	0.2677	0.2657
13	0.0228	0.2278
14	0.1907	0.1897
16	0.1511	0.1519
18	0.1219	0.1214
19	0.1067	0.1062
20	0.9017	0.0912